

# Lincoln Mark VII

## EEC-IV

C—Continuous code  
 O—key On test code  
 R—engine Running test code

<b>Error Code</b>	<b>Description</b>	<b>Type</b>
<b>11</b>	System Pass	<b>C/O/R</b>
<b>12</b>	RPM Not Within Self Test Upper Limit	<b>R</b>
<b>13</b>	RPM Not Within Self Test Lower Limit	<b>R</b>
	DC Motor Did Not Move	<b>C/O/R</b>
<b>14</b>	Profile Ignition Pickup Circuit Failure	<b>C</b>
	Engine RPM Sensor Circuit Fault (Diesel)	<b>C</b>
<b>15</b>	Readout Memory Test Failed	<b>O</b>
	Keep Alive Memory Test Failed	<b>C</b>
<b>16</b>	Ignition Diagnostic Module (2.9L, 3.0L & 4.0L)	<b>O</b>
	Idle RPM High With ISC Retracted (2.5L)	<b>R</b>
	RPM Above Self Test Limit With ISC Off (1986–90 1.9L EFI)	<b>R</b>
	RPM Too Low To Perform HO2S Test (Others)	<b>R</b>
<b>17</b>	Idle RPM Low With ISC Retracted (1.9L & 2.5L CFI)	<b>R</b>
	RPM Below Self Test Limit With ISC Off (1986–90 1.9L EFI)	<b>R</b>
<b>18</b>	Spark Out (SPOUT) Circuit Open	<b>R</b>
	Loss Of Ignition Diagnostic Module Input To PCM/SPOUT Circuit Grounded	<b>C</b>
	Spark Angle Word (SAW) Circuit Failure (1.9L SFI)	<b>C/R</b>
<b>19</b>	Failure In PCM Internal Voltage	<b>R</b>
	Erratic RPM During Hard Idle Self Test	<b>R</b>
	RPM Drop Too Low During ISC Off Test (1.9L EFI)	<b>R</b>
	Power Processor Check (2.3L HSC EFI)	<b>O</b>
	Cylinder Identification Sensor Input Failure (3.0L SHO)	<b>C</b>
<b>21</b>	Engine Coolant Temperature (ECT) Sensor Out Of	<b>O/R</b>

Lincoln Mark VII EECIV Codes

	Self Test Range	
22	Manifold Absolute Pressure/Barometric Pressure Sensor Out Of Self Test Range	C/O/R
23	Throttle Position Sensor Out Of Self Test Range	C/O/R
	Fuel Injector Pump Lever Sensor Input Is Out Of Self Test Range (Diesel)	O/R
24	Intake Air Temperature/Air Charge Temperature Sensor Out Of Self Test Range	O/R
25	Knock Not Sensed During Dynamic Response Test	R
26	Mass Air Flow/Vane Air Flow Sensor Out Of Self Test Range	O/R
	transmission Fluid Temperature Sensor Input Out Of Self Test Range (5.0L, 5.8L, 7.3L & 7.5L truck)	O/R
27	Vehicle Speed Sensor (2.3L Turbo)	C
28	Loss Of Ignition Diagnostic Module RH Side	C
	Vane Air Temperature Sensor Input Out Of Self Test Range (1.9L EFI)	O/R
29	Insufficient Input From Programmable Speedometer/Odometer Module (From 1993)	C
	Insufficient Input From Vehicle Speed Sensor (To 1992)	C
31	EGR Valve Position/Pressure Feedback EGR Circuit Below Minimum Voltage	C/O/R
32	EGR Not Controlling (2.3L OHC & 3.8L CFI)	R
	EGR Valve Not Seated (1.9L CFI, 2.9L & 3.0L SHO)	C/R
	EGR Valve Position/Pressure Feedback EGR Voltage Below Closed Voltage (Others)	C/O/R
33	EGR Not Closing Properly (2.3L OHC & 3.8L CFI)	C/R
	Throttle Position Sensor Noisy/Harsh On Line (Diesel)	C
	EGR Valve Opening Not Detected (Others)	C/R
34	EGR Valve Opening Not Detected (2.3L OHC & 3.8L CFI)	R
	Defective EGR Pressure transducer Sensor (1.9L CFI, 2.3L HSC EFI & 3.0L)	C/O/R
	EGR On/Off Control (2.3L Turbo)	R
	EGR Valve Position/Pressure Feedback EGR Voltage Above Closed Limit (Others)	C/O/R

Lincoln Mark VII EECIV Codes

<b>35</b>	RPM Too Low To Perform EGR Test (2.3L OHC & 3.8L CFI) EGR Valve Position/EGR Pressure Feedback EGR Circuit Above Maximum Voltage (Others)	<b>R</b> <b>C/O/R</b>
<b>36</b>	System Indicates Lean At Idle	<b>R</b>
<b>37</b>	System Indicates Rich At Idle	<b>R</b>
<b>38</b>	DC Motor Idle Speed Control/Idle tracking Throttle Position Sensor Open Circuit (2.3L CFI & 2.5L HSC)	<b>C</b>
<b>39</b>	AXOD Converter Bypass Clutch Not Applying Properly	<b>C</b>
<b>41</b>	System Indicates Lean No HO2S Switching Detected	<b>R</b> <b>C</b>
<b>42</b>	System Indicates Rich No O2S Switching Detected	<b>R</b> <b>C</b>
<b>43</b>	HO2S Lean At Wide Open Throttle (1986–90 1.9L MFI) Throttle Position Sensor Below Idle Sped (Diesel)	<b>C</b> <b>C</b>
<b>44</b>	Secondary Air System Inoperative	<b>R</b>
<b>45</b>	Secondary Air Upstream During Self Test Coil 1 Primary Circuit Failure (1990–91 1.9L EFI/SFI, ) Distributorless Ignition System Coil Pack 3 Circuit Failure (3.0L SHO 3.8L SC)	<b>R</b> <b>C</b> <b>C</b>
<b>46</b>	Secondary Air Not Bypassed During Self Test Coil 2 Primary Circuit Failure (1990–91 1.9L MFI/SFI) Distributorless Ignition System Coil Pack 1 Circuit Failure (3.0L SHO 3.8L SC)	<b>R</b> <b>C</b> <b>C</b>
<b>47</b>	4 X 4 Switch Is Closed Measured Air Flow Low At Base Idle	<b>O</b> <b>R</b>
<b>48</b>	Loss Of Ignition Diagnostic Monitor LH Side (2.3L) Measured Air Flow High At Base Idle (1986–90 1.9L EFI) Distributorless Ignition System Coil Pack 2 Circuit Failure (3.0L SHO 3.8L SC)	<b>C</b> <b>R</b> <b>C</b>
<b>49</b>	Spark Output (SPOUT) Signal Default To 10°. BDTC (3.0L SHO & 3.8L SC) 1–2 Shift Error (Others)	<b>C</b> <b>C</b>
<b>51</b>	Engine Coolant Temperature Circuit Open	<b>O/C</b>
<b>52</b>	Power Steering Pressure Switch Circuit Open	<b>O</b>

Lincoln Mark VII EECIV Codes

	Power Steering Pressure Switch Circuit Did Not Change States	<b>R</b>
<b>53</b>	Throttle Position Sensor Circuit Above Maximum Voltage	<b>C/O</b>
	Fuel Injector Pump Lever Sensor Input Is Greater Than Self Test (Diesel)	<b>C/O</b>
<b>54</b>	Intake Air Temperature/Air Charge Temperature Circuit Open	<b>C/O/R</b>
<b>55</b>	Key Power Check	<b>R</b>
<b>56</b>	transmission Fluid Temperature Circuit Open	<b>C/O</b>
	Mass Air Flow/Vane Air Flow Sensor Circuit Above Maximum Voltage	<b>C/O/R</b>
<b>57</b>	transaxle Neutral Position Switch Circuit Failed Open	<b>C</b>
<b>58</b>	Idle tracking Switch Circuit Open Or Grounded (CFI)	<b>O/R</b>
	Vane Air Temperature Sensor Input Greater Than Self Test Maximum (EFI)	<b>C/O</b>
<b>59</b>	AXOD Neutral Position Switch Circuit Failed Open (3.0L & 3.8L)	<b>C</b>
	2-3 Shift Error (Others)	<b>C</b>
	Low Speed Fuel Pump Circuit Failure, Battery To PCM (3.0L SHO)	<b>C/O</b>
	AXOD 4/3 Pressure Switch Circuit Failed Closed	<b>O</b>
	AXOD 4/3 Pressure Switch Circuit Failed Open	<b>C</b>
<b>61</b>	ECT Sensor Circuit Grounded	<b>C/O/R</b>
<b>62</b>	Torque Converter Clutch Error	<b>C</b>
	AXOD 4/3 Or 3/2 Pressure Switch Circuit Grounded	<b>O</b>
<b>63</b>	Throttle Position Sensor Circuit Below Minimum Voltage	<b>C/O/R</b>
	Fuel Injection Pump Lever Sensor Input Is Less Than Self Test Min. (Diesel)	<b>C/O</b>
<b>64</b>	Intake Air Temperature/Air Charge Temperature Circuit Grounded	<b>C/O/R</b>
<b>65</b>	transmission Control Switch/Overdrive Cancel Switch Circuit Did Not Change States	<b>R</b>
	Fuel Control (2.3L Turbo)	<b>C</b>
<b>66</b>	Mass Air Flow Sensor Circuit Below Minimum Voltage (Except 1.9L MFI & 2.3L Turbo)	<b>C</b>
	Vane Air Flow Sensor Input Less Than Self Test Minimum (1.9L MFI & 2.3L Turbo)	<b>O/C</b>

Lincoln Mark VII EECIV Codes

	transmission Fluid Temperature Circuit Grounded (Others)	<b>O/C</b>
<b>67</b>	Park Neutral Position Switch Circuit Open; A/C On (Manual)	<b>O</b>
	Manual Lever Position Sensor Out Of Range/A/C On	<b>O/C</b>
	Clutch Switch Circuit Failure	<b>C</b>
	A/C Input High (2.5L TBI)	<b>O/C</b>
<b>68</b>	Idle tracking Switch Closed (1.9L, 2.3L, 2.5L & 3.8L CFI)	<b>O/R</b>
	Vane Air Temperature Sensor Input Less Than Self Test Minimum (1.9L MFI & 2.3L Turbo)	<b>O/C</b>
	transmission Fluid Temperature transmission Over Temp (Overheated) (Diesel)	<b>C</b>
<b>69</b>	3-4 Shift Error	<b>C</b>
	AXOD Neutral Position Switch Failed Open (3.0L)	<b>C</b>
	AXOD 3/2 Pressure Switch Failed Closed (3.8L SFI)	<b>C/O</b>
<b>70</b>	EEC IV Data transaxle Circuit Failed (3.8L SFI)	<b>C</b>
<b>71</b>	Idle tracking Switch Closed On Pre-Position (1.9L, 2.3L & 2.5L CFI)	<b>C</b>
	Software Re-Initialization Detected (1.9L EFI)	<b>C</b>
	Cluster center Control Circuit Failed (3.8L SFI)	<b>C</b>
<b>72</b>	Insufficient Manifold Absolute Pressure/Mass Air Flow Change During Dynamic Response Test	<b>R</b>
	Power Interrupt Software Re-Initialization Detected (1.9L & 2.3L Turbo)	<b>C</b>
	Message center Control Assembly Circuit Failed (3.8L SFI)	<b>C</b>
<b>73</b>	Insufficient Throttle Position Change During Dynamic Response Test	<b>O/R</b>
<b>74</b>	Brake On/Off Circuit Open-Not During Self Test	<b>R/C</b>
<b>75</b>	Brake On/Off Circuit Closed/ECA Input Open	<b>R</b>
<b>76</b>	Insufficient Vane Air Flow Sensor Output Change During Dynamic Response Test	<b>R</b>
<b>77</b>	Operator Error Dynamic Response Test	<b>R</b>
<b>78</b>	Re-Initialization Check	<b>R</b>
<b>79</b>	A/C On/Defrost On During Self Test	<b>O</b>
<b>81</b>	Secondary Air Diverter Circuit Failure	<b>O</b>
	Turbo Boost (2.3L Turbo)	<b>O</b>
	Insufficient IAS Output Voltage Change When	<b>O</b>

Lincoln Mark VII EECIV Codes

	Solenoid Is Activated (3.0L SHO)	
<b>82</b>	Secondary Air Bypass Circuit Failure	<b>O</b>
	Integrated Relay Control Module (2.3L Turbo)	<b>O</b>
	Supercharger Bypass Circuit Failure (3.8L SC)	<b>O</b>
<b>83</b>	Integrated Relay Control Module (2.3L Turbo & 2.5L)	<b>O</b>
	High Electric Drive Fan Circuit Failure (1.9L & 2.5L SFI)	<b>O</b>
	EVP/EGRC/EGRV (2.3L OHC & 3.8L CFI)	<b>O</b>
	Low Speed Fuel Pump Relay Circuit Open (3.0L SHO)	<b>C/O</b>
	Integrated Relay Control Module (3.8L Turbo)	<b>O</b>
	High Electric Drive Fan Circuit Failure (3.8L SFI & 3.8L SC)	<b>O</b>
<b>84</b>	EGR Valve Position/Pressure Feedback EGR/EGR Control Circuit Failure	<b>O</b>
<b>85</b>	Adaptive Fuel Lean Limit Reached (1.9L EFI)	<b>C</b>
	Shift Solenoid 3/4–4/3 (2.3L Turbo)	<b>O</b>
	CANP Circuit Failure (Others)	<b>O</b>
<b>86</b>	Shift Solenoid Circuit Failure (2.9L 3.0L & 4.0L)	<b>O</b>
	Adaptive Fuel Rich Limit Reached (1.9L EFI)	<b>C</b>
<b>87</b>	Primary Fuel Pump Circuit Failure	<b>O/C</b>
	Integrated Relay Control Module (2.3L Turbo & 2.5L & 3.8L MFI)	<b>O</b>
<b>88</b>	Loss Of Dual Plug Input Control	<b>C</b>
	Shift Solenoid 3/4–4/3 (2.3 Turbo)	<b>O</b>
	Integrated Relay Control Module (2.5 L HSC & 3.8L EFI)	<b>O</b>
	Electric Drive Fan Circuit Failure (2.5L, 3.0L SHO & 3.8L SFI)	<b>O</b>
	Throttle Kicker Fault (5.0L)	<b>—</b>
<b>89</b>	Converter Clutch Override Circuit Failure (2.9L, 3.0L & 4.0L)	<b>O</b>
	Exhaust Heat Control (3.8L CFI)	<b>O</b>
<b>91</b>	Shift Solenoid 1 Circuit Failure	<b>O</b>
	HO2S Circuit Indicates Lean	<b>R</b>
	No HO2S Switching Detected	<b>C</b>
<b>92</b>	Shift Solenoid 2 Circuit Failure	<b>O</b>
	HO2S Circuit Indicates Rich	<b>R</b>
<b>93</b>	Throttle Position Sensor Input Low At Maximum D.C. Motor Extension (1.9L, 2.3L & 2.5L TBI)	<b>O</b>

## Lincoln Mark VII EECIV Codes

	Converter Clutch Solenoid Circuit Failure (Others)	<b>O</b>
<b>94</b>	Torque Converter Clutch Solenoid Circuit Failure	<b>O</b>
	Secondary Air Injection Inoperative	<b>R</b>
<b>95</b>	Integrated Relay Control Module (2.5L HSC & 3.8L EFI)	<b>C/O</b>
	Fuel Pump Circuit Open-PCM To Motor Ground (Others)	<b>C/O</b>
<b>96</b>	Integrated Relay Control Module (2.5L HSC & 3.8L EFI)	<b>C/O</b>
	High Speed Fuel Pump Relay Circuit Open (3.0L SHO)	<b>C/O</b>
	Fuel Pump Circuit Open-Battery To PCM (Others)	<b>C/O</b>
<b>97</b>	transmission Control Indicator Lamp Circuit Failure	<b>O</b>
<b>98</b>	Hard Fault Present	<b>R</b>
	Electronic Pressure Control Driver Open In PCM (Diesel)	<b>O</b>
<b>99</b>	Electronic Pressure Control Circuit Failure	<b>O/C</b>
	Electronic Engine System Has Not Learned To Control Idle	<b>R</b>